



hardware handshake
utilize interrupt inputs
connect CF interrupt to one of inputs

Use R/V instead
Bring in DTACKS

Two 1x20 headers because bug in
VinBoard that can't rotate 180 degree

CB030, Rev1 with 16-bit CF
A MC68030 SBC in 100mm x 100mm
Apr 2020
©2020 H. Shen